

## The Ohio Public Works Commission 65 East State Street, Suite 312, Columbus, Ohio 43215 Phone (614) 466-0880

## CB03B

## APPLICATION FOR FINANCIAL ASSISTANCE Revised 7/93

proper completion of this form.	tions for Completion of Project Application" for assistance in the
SUBDIVISION: City of Cincinnati	CODE#_061-15000_
DISTRICT NUMBER: 2 COUNTY: Hamilton	on DATE 9 / 22 / 97
CONTACT: Chris Nyberg, P.E. (THE PROJECT CONTACT PERSON SHOULD BE THE INDIVIDUAL WHO W SELECTION PROCESS AND WHO CAN BEST ANSWER OR COORDINATE	ILL BE AVAILABLE ON A DAY-TO-DAY BASIS DURING THE APPLICATION REVIEW AND
PROJECT NAME: West Fork Road Alig	nment and Bridge Replacements
SUBDIVISION TYPE         FUNDING TYPE           (Check Only 1)         (Check All Requested & X_1. Grant \$ 1,42          1. County        2. Loan \$	
TOTAL PROJECT COST: \$2,040,000.00 FUNDIN	NG REQUESTED: \$ 1,428,000.00
	RECOMMENDATION the District Committee ONLY
To be completed by GRANT: \$ 1,428,000.00	the District Committee ONLY  LOAN ASSISTANCE: \$
GRANT: \$ 1,428,000.00  LOAN: \$  (Check Only 1)  X State Capital Improvement Program  Local Transportation Improvements Program	the District Committee ONLY  LOAN ASSISTANCE: \$ % TERM:yrs. (Attach Loan Supplement)  DISTRICT MBE SET-ASIDE Construction \$
GRANT: \$_1,428,000.00 LOAN: \$  (Check Only 1)  X State Capital Improvement Program Local Transportation Improvements Program Small Government Program	the District Committee ONLY  LOAN ASSISTANCE: \$ % TERM:yrs. (Attach Loan Supplement)  DISTRICT MBE SET-ASIDE Construction \$

#### MBE Force Account 1.1 PROTECT ESTIMATED COSTS: \$ \$ (Round to Nearest Dollar) Project Engineering Costs: a.) Preliminary Engineering 1. .00 2. Final Design .00 Other Engineer Services \* 3. .00 \$ Supervision .00 Miscellaneous \$ .00 b.) Acquisition Expenses: 1. Land .00 2. Right-of-Way .00 c.) Construction Costs: \$1,850,000.00 d.) Equipment Purchased Directly: .00 e.) Other Direct Expenses: .00 Contingencies: f.) \$ 190,000.00 g.) TOTAL ESTIMATED COSTS: \$2,040,000.00 1.2 PROJECT FINANCIAL RESOURCES: (Round to Nearest Dollar and Percent) % Local In-Kind Contributions a.) \$ .00 Local Public Revenues \$612,000.00 b.) 30 Local Private Revenues c.) .00 d.) Other Public Revenues 1. ODOT PID# \_\_\_ .00 2. EPA/OWDA .00 3. OTHER .00 SUB TOTAL LOCAL RESOURCES: \$ 612,000.00 30 **OPWC Funds** e.) 1. Grant \$1,428,000.00 <u>70</u> 2. Loan \$ .00 3. Loan Assistance .00 SUB TOTAL OPWC RESOURCES: \$ 1,428,000.00 70 f.) TOTAL FINANCIAL RESOURCES: \$ 2,040,000.00 100% \*Other Engineer's Services must be outlined in detail on the required certified engineer's estimate.

PROJECT FINANCIAL INFORMATION

1.3 AVAILABILITY OF LOCAL FUNDS:

1.0

Attach a summary from the <u>Chief Financial Officer</u> listed in section 5.2 listing <u>all local share funds</u> budgeted for the project and the date they are anticipated to be available.

## 2.0 PROJECT INFORMATION

IMPORTANT: If project is multi-jurisdictional, information must be consolidated in this section.

- 2.1 PROJECT NAME: West Fork Road Alignment and Bridge Replacements
- 2.2 PROJECT DESCRIPTION (Sections a through d):
  - a: SPECIFIC LOCATION: West Fork Road, 1/4 Mile North of Montana Ave.

PROJECT ZIP CODE: 45211

## b: PROJECT COMPONENTS:

This project involves the realignment of West Fork Road for improved safety. The complete replacement of two bridges with improved alignments is included with the work. The two proposed bridges will be single span, precast concrete box beam bridges with drilled shaft supported abutments.

## c: PHYSICAL DIMENSIONS / CHARACTERISTICS:

## SOUTH BRIDGE

Existing length = 28.0'
Existing width = 34.0'
(24' roadway, 1- 6.0' walk)
Proposed length = 32.0'
Proposed width = 38.0'
(28.0' roadway, 1-6.0' walk)

## **NORTH BRIDGE**

Existing length = 88.0'
Existing width = 34.0'
(24' roadway, 1-6.0' walk)
Proposed length = 56.0'
Proposed width = 38.0'
(28.0' roadway, 1-6.0' walk)

## ROADWAY

Approximately 850' of roadway will be realigned and widened (from 22.0' to 28.0') to improve sight distance around the proposed bridges and replace a compound curve with a single larger radius curve.

## d: DESIGN SERVICE CAPACITY:

IMPORTANT: Detail shall be included regarding current service capacity vs proposed service level. If road or bridge project, include ADT. If water or wastewater project, include both current residential rates based on monthly usage of 7,756 gallon per household. Attach current rate ordinance.

1992 ADT = 4585 vehicles/day 2017 ADT = 6547 vehicles/day (estimated)

## 2.3 USEFUL LIFE / COST ESTIMATE:

Project Useful Life: 50 Years.

Attach <u>Registered Professional Engineer's</u> statement, with <u>original seal and signature</u> certifying the project's useful life indicated above and estimated cost.

## 3.0 REPAIR/REPLACEMENT or NEW/EXPANSION:

TOTAL PORTION OF PROJECT REPAIR/REPLACEMENT \$<u>2,040,000</u> <u>100</u>% State Funds Requested for Repair and Replacement \$\_1,428,000 70% TOTAL PORTION OF PROJECT NEW/EXPANSION State Funds Requested for New and Expansion (SCIP Project Grant Funding for New and Expansion cannot exceed 50% of the total Project Costs.) PROTECT SCHEDULE:\* 4.0 **BEGIN DATE END DATE** 4.1 Engineering/Design: 10/1/97 7/1/98 4.2 Bid Advertisement: 7/1/98 8/1/98 4.3 Construction: 10/1/98 10/1/99 \* Failure to meet project schedule may result in termination of agreement for approved projects. Modification of dates must be approved in writing by the Commission once the Project Agreement has been executed. Dates should assume project agreement approval/release on July 1st. of the Program Year applied for. 5.0 APPLICANT INFORMATION: **=** 1 בת דורות דישור לישור ווייות דיש

5.1	CHIEF EXECUTIVE OFFICER TITLE STREET CITY/ZIP PHONE FAX	John Shirey City Manager Room 152, City Hall, 801 Plum Street Cincinnati, Ohio 45202 ( 513 ) 352 - 3241 ( ) -
5.2	CHIEF FINANCIAL OFFICER TITLE STREET CITY/ZIP PHONE FAX	Frank A. Dawson Director of Finance Room 250, City Hall, 801 Plum Street Cincinnati, Ohio 45202 ( 513 ) 352 - 3731 ( ) -
5.3	PROJECT MANAGER TITLE STREET CITY/ZIP PHONE FAX	Jay Gala, P.E. Principal Construction Engineer Room 415, City Hall, 801 Plum Street Cincinnati, Ohio 45202 ( 513 ) 352 - 3423 ( 513 ) 352 - 1581

## 6.0 ATTACHMENTS/COMPLETENESS REVIEW:

Check each section below, confirming that all required information is included in this application.
XA certified copy of the legislation by the governing body of the applicant authorizing a designated official to submit this application and execute contracts. (Attach)
XA summary from the applicant's Chief Financial Officer listing all local share funds budgeted for the project and the date they are anticipated to be available. (Attach)
A registered professional engineer's estimate of projects useful life and cost estimate, as required in 164-1-14 and 164-1-16 of the Ohio Administrative Code. Estimates shall contain engineer's original seal and signature. (Attach)
A copy of the cooperation agreement(s) if this project involves more than one subdivision or district.(Attach)
<ul> <li>Capital Improvements Report: (Required by 164 O.R.C. on standard form)</li> <li>A: Attached.</li> <li>B: Report/Update Filed with the Commission within the last twelve months.</li> </ul>
J. Report Opulie Fried with the Commission within the last twelve months.
//A Floodplain Management Permit: Required if project is in 100 year floodplain. See Instructions.
Supporting Documentation: Materials such as additional project description, photographs, economic impact (temporary and/or full time jobs likely to be created as a result of the project), and other information to assist your district committee in ranking your project.
7.0 APPLICANT CERTIFICATION:
The undersigned certifies that: (1) he/she is legally authorized to request and accept financial assistance from the Ohio Public Works Commission; (2) that to the best of his/her knowledge and belief, all representations that are part of this application are true and correct; (3) that all official documents and commitments of the applicant that are part of this application have been duly authorized by the governing body of the applicant; and, (4) should the requested financial assistance be provided, that in the execution of this project, the applicant will comply with all assurances required by Ohio Law, including those involving minority business utilization, Buy Ohio, and prevailing wages.
IMPORTANT: Applicant certifies that physical construction on the project as defined in the application has NOT begun, and will not begin until a Project Agreement on this project has been executed with the Ohio Public Works Commission. Action to the contrary will result in termination of the agreement and withdrawal of Ohio Public Works Commission funding of the project.
John Shirey, City Manager Certifying Regresentative (Type or Print Name and Title)
Signature/Date Signed

# City of Cincinnati



Department of Public Works Division of Engineering

Room 440, City Hall 801 Plum Street Cincinnati, Ohio 45202

John Hamner Director

Prem Garg, P.E. City Engineer

September 5, 1997

Subject:

West Fork Road: Safety Upgrade and Bridge Replacements

Certification of Useful Life for OPWC Projects

As required by Chapter 164-1-13 of the Ohio Administrative Code, I hereby certify that the design useful life of the subject street and bridge improvement is at least 50 years.

Prem Garg, P.E. City Engineer

City of Cincinnati

## ITEMIZED BRIDGE PROJECT COST ESTIMATE: WEST FORK ROAD: SAFETY UPGRADE & BRIDGE REPLACEMENTS

	ITEM						
=	NO.	DESCRIPTION	QUAN	TITIES	LABOR	MATERIALS	ITEM TOTAL
	103	Contract Bond	Lump	Sum	12,000.00	0.00	12,000
	201	Clearing & Grubbing	Lump	Sum	15,000.00	20,000.00	35,000
	202	Wearing Course Removed	270	Sq. Yd.	15.00	0.00	4,050
	202	Asphalt Pavement Removed	1,890	Sq. Yd.	10.00	0.00	18,900
	202	Concrete Walk Removed	480	Sq. Ft.	1.00	0.00	480
	202	Obstructions Removed	Lump	Sum	15,000.00	0.00	15,000
	202	Structures Removed, South Bridge	Lump	Sum	30,000.00	15,000.00	45,000
	202	Structures Removed, North Bridge	Lump	Sum	50,000.00	25,000.00	75,000
	202	Pipe Removed, 18" W.M.	825	Lin. Ft.	8.00	8.00	13,200
	202	Pipe Removed, 12" Sewer	248	Lin. Ft.	6.00	6.00	2,976
	202	Manholes Removed	2	Each	350.00	100.00	900
	202	Guardrail Removed	243	Lin. Ft.	1.00	1.00	486
	202	T-Wall Removed for Reuse	1,282	Sq. Ft.	4.00	2.00	7,692
•	203	Embankment	982	Cu. Yd.	7.00	7.00	13,748
J	203	Excavation, Not Including Embankment	342	Cu. Yd.	5.00	3.00	2,736
200 2 4 5	. 2031	Subgrade Compaction	1,876	Sq. Yd.	2.00	1.00	5,628
11. 11. 15. 15. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	205	Special Fill Material, Gravel Bedding	20	Tons	25.00	5.00	600
ty. +	301	Bituminous Aggregate Base, 8"	418	Cu. Yd.	30.00	60.00	37,620
***	304	Aggregate Base, 6"	200	Cu. Yd.	20.00.	40.00	12,000
Saturation of the	404	Asphalt Concrete, 2" Surface Course	150	Cu. Yd.	20.00	55.00	11,250
. 3.175	503.	Cofferdams, Cribs & Sheeting	Lump	Sum	25,000.00	25,000.00:	50,000
	503	Unclassified Excavation, Overburden	1,900	Cu. Yd.	. 10.00	10,00	38,000
	504	Unclassified Excavation, Including Shale	2,000	Cu. Yd.	15.00	10.00	50,000
	508	Pier Forms, 30"	1,000	Lin. Ft.	8.00	8.00	16,000
	510	Dowel Holes	64	Each	7.00	7.00	896
	511	Class C Concrete, Wingwalls	107	Cu. Yd.	280.00	100.00	40,660
	511	Class C Concrete, Wall Footings	97	Cu. Yd.	155.00	100,00	24,735
	511	Class C Concrete, Channel Walls	216	Cu. Yd.	280.00	100.00	82,080
	511	Class C Concrete, Channel Floor	455	Cu. Yd.	155.00	100.00	116,025
	511	Class C Concrete, Weir	25	Cu. Yd.	280.00	100.00	9,500
	511	Class S Concrete, Facia Panels	1,240	Sq. Ft.	7.00	7.00	17,360
	512	Waterproofing, Type A	51	Sq. Yd.	15.00	15.00	1,530
	512	Waterproofing, Type B	245	Sq. Yd.	20.00	15.00	8,575
	515	Prestressed Concrete Box Beams, 32'	8	Each	1,000.00	5,000.00	48,000

	_	æ

NO.	DESCRIPTION	QUAN <sup>*</sup>	TITIES	LABOR	MATERIALS	ITEM TOTAL
515	Prestressed Concrete Box Beams, 55'	8	Each	1,000.00	7,000.00	64,000
517	Railing, Class S Concrete	464	Lin. Ft.	100.00	60.00	74,240
518	Porous Backfill with Filter Fabric	885	Cu. Yd.	20.00	20.00	35,400
524	Drilled Shafts, 30"	2,058	Lin. Ft.	15.00	45.00	123,480
601	Riprap, Grouted	355	Cu. Yd.	20.00	50.00	24,850
602	Stone Masonry	4,120	Sq. Ft.	10.00	8.00	74,160
603	12" Conduit, Type B	256	Lin. Ft.	25.00	25.00	12,800
604	Manholes, Type S	2	Each	2,000.00	2,000.00	8,000
606	Guardrail, Type 5	250	Lin. Ft.	8.00	8.00	4,000
606	Bridge Terminal Assembly, Type 2	8	Each	400.00	400.00	6,400
608	Concrete Walk, 5"	480	Sq. Ft.	2.00	2.00	1,920
609	Concrete Curb, Type B-1	80	Lin. Ft.	6.00	6.00	960
611	Reinforced Concrete Approach Slab (12")	193	Sq. Yd.	60.00	70.00	25,090
611	Reinforced Concrete Approach Walks (7")	40	Sq. Yd.	40.00	50.00	3,600
611	Reinforced Concrete Sleeper Slabs (8")	103	Sq. Yd.	40,00	50.00	9,270
614	Maintaining Traffic	Lump	Sum	10,000.00	10,000.00	20,000
609	Field Office	Lump	Sum	500.00	4,500.00	5,000
659	Seeding and Mulching	1,599	Sq. Yd.	1.00	1.00	3,198
1101	Furnish & Lay 18" Ductile fron Pipe	1,000	Lin. Ft.	75.00	75.00	150,000
1102	Hauling Water Works Material	Lump	Sum :	100.00	100.00	200
1110	Concrete, Class C	50	Cu. Yd.	50.00	50.00	5,000
1119	Additional Excavation	60	Cu. Yd.	10.00	10.00	1,200
1120	Exploratory Excavation	. 60	Cu. Yd.	10.00	10.00	1,200
Special	Low Density Concrete Fill	2,777	Cu. Yd.	30.00	30.00	166,620
Special	Modular Unit Wall (T-Wall)	3,500	Sq. Ft.	10.00	15.00	87,500
Special	Select Granular Backfill	1,167	Cu. Yd.	10.00	25.00	40,845
Special	High Performance Concrete, Abutments	34	Cu. Yd.	200.00	200.00	13,600
Special	High Performance Concrete, Superstructur	100	Cu. Yd.	250.00	250.00	50,000
Special	High Performance Concrete, Trial Mix	Lump	Sum	600.00	600.00	1,200
Special	High Performance Concrete, Testing	Lump	Sum	2,500.00	2,500.00	5,000
Special	Sealing Concrete Surfaces, Superstructure	900	Sq. Yd.	5.00	5.00	9,000
Special	Sealing Concrete Surfaces, Railing	464	Lin. Ft.	5.00	5.00	4,640
Special	10% Estimated Contingencies					190,000

TOTAL: \$2,040,000

F C C C

Prem Garg, PE City Engineer City of Cincinnati

# City of Cincinnati



Department of Finance

September 19, 1997

Room 250, City Hall 801 Plum Street Cincinnati, Ohio 45202

F. A. Dawson Director

J.L. Andreyko
Deputy Director

Mr. Laurence Bicking, Director Ohio Public Works Commission 65 East State Street, Suite 312 Columbus, Ohio 43215

RE: Status of Funds for Local Share of 1998 SCIP/LTIP Project Grants

Dear Mr. Bicking:

The local matching share for the following 1998 SCIP/LTIP Projects (Round 12 Funding) are recommended by the City Manager for funding in the City's 1998 Capital Improvement Program:

## STREET REHABILITATIONS

- 1. Vine Street (North) Paddock Road to North Corporation Line
- 2. Madison Road (South) Observatory Avenue to Edwards Road
- 3. Spring Grove Avenue Mitchell Avenue to North Corporation Line
- 4. Ludlow Avenue Cornell Place to Central Parkway
- 5. Rutledge/St. Lawrence Avenues St. William Avenue to Rapid Run Pike
- 6. Anderson Ferry Road Hillside Avenue to Corporation Line
- 7. Duck Creek Road Red Bank Road to Oaklawn Drive
- 8. Glenway Avenue Boudinot Avenue to Werk Road
- 9. Madison Road (North) Edwards Road to Brotherton Road
- 10. Vine Street (South) Clifton Avenue to McMillan Street
- 11. Crawford Avenue Dane Avenue to Springlawn Avenue
- 12. Wasson Road Paxton Road to Edwards Road
- 13. North Bend Road Argus Road to Hamilton Avenue
- 14. Quebec Road Glenway Avenue to Westwood Avenue

## STREET IMPROVEMENTS & WIDENINGS

- 15. Southside Avenue Improvement Phase II
- 16. Eastern Avenue Widening Eggleston Avenue to Bains Place
- 17. East Epworth Chickering Avenue to West Mitchell Avenue
- 18. Pete Rose Way Central Avenue to Elm Street
- 19. Mehring Way Central Avenue to Roebling Bridge
- 20. Queen City Avenue LaFeuille Avenue to Werk Road
- 21. Red Bank Road Woodford Road to Zinsle Avenue

## BRIDGE REPLACEMENT PROJECTS

- 22. Dreman Avenue over West Branch of Millcreek
- 23. Gest Street Bridge over CIND Railroad
- 24. West Fork Road Improvement & Bridge Replacement

## RETAINING WALL REHABILITATION PROJECT

25. Columbia Parkway - Wall "D" Rehabilitation

## LANDSLIDE CORRECTION PROJECT

26. Lehman Road Landslide Correction

The matching funds for these projects are coming from Street Improvement Bonds which are scheduled for sale in the early part of 1998.


If you have any questions or need additional information, please contact me at 513-352-3731.

Sincerely,

F. A. Dawson

Director of Finance

F& Dawson



# M.G.V.

## City of Cincinnati

## An Ordinance No. 330

- 1997

AUTHORIZING the City Manager to apply for and accept street rehabilitation, street improvement and widening, bridge replacement, landslide correction, and retaining wall rehabilitation funding grants from the State of Ohio, Ohio Public Works Commission, in the approximate amount of \$16,315,580, and to execute any agreements necessary for the receipt and administration of said grants.

WHEREAS, the State Capital Improvement Program and Local Transportation Improvement Program provide for infrastructure funding; and

WHEREAS, the District 2 Integrating Committee is accepting applications for projects within Hamilton County, State of Ohio; and

WHEREAS, the City of Cincinnati has the required \$8.2 million in matching funds for 1998, for fourteen (14) street rehabilitation projects, namely Anderson Ferry Road, Crawford Avenue, Duck Creek Road, Glenway Avenue, Ludlow Avenue, two sections of Madison Road, North Bend Road, Quebec Road, Rutledge & Saint Lawrence Avenues, Spring Grove Avenue, two sections of Vine Street, and Wasson Road; seven (7) street improvement and widening projects, namely East Epworth Avenue, Eastern Avenue, Mehring Way, Pete Rose Way, Queen City Avenue, Red Bank Road, and Southside Avenue; three (3) bridge replacement projects, namely Dreman Avenue, Gest Street over the CIND Railroad, and West Fork Road; rehabilitation of Retaining Wall "D" along Columbia Parkway; and a landslide correction project on Lehman Road; now, therefore,

BE IT ORDAINED by the Council of the City of Cincinnati, State of Ohio:

Section 1. That the City Manager is hereby authorized to execute and file applications, on behalf of the City of Cincinnati, with the Ohio Public Works Commission through the Hamilton County District 2 Integrating Committee, for grants in the approximate amount of \$16,315,580 for funding fourteen (14) street rehabilitation projects, namely Anderson Ferry Road, Crawford Avenue, Duck Creek Road, Glenway Avenue, Ludlow Avenue, two sections of Madison Road, North Bend Road, Quebec Road, Rutledge &

Saint Lawrence Avenues, Spring Grove Avenue, two sections of Vine Street, and Wasson Road; seven (7) street improvement and widening projects, namely East Epworth Avenue, Eastern Avenue, Mehring Way, Pete Rose Way, Queen City Avenue, Red Bank Road, and Southside Avenue; three (3) bridge replacement projects, namely Dreman Avenue, Gest Street over the CIND Railroad, and West Fork Road; rehabilitation of Retaining Wall "D" along Columbia Parkway; and a landslide correction project on Lehman Road; and to accept such grants if awarded by the Ohio Public Works Commission.

Section 2. That the City Manager is hereby authorized to execute such agreements and other documents as are required by the State for receipt and administration of the above grants.

Section 3. This ordinance shall take effect from and after the earliest period allowed by law.

Passed eptember / T A.D.,

Mayor

Attes

Clerk

I HEREBY CERTIFY THAT UNDIN ANCE NO

1997 WAS PUBLISHED IN THE CITY SUILLET IN

ACCORDANCE WITH THE CHARTER ON 2-30-

Clerk of Council.

Signature:  Bridge #: COUNTY #70	ERIDGE NAME/ANSPECTION THEM SOME AS A SECOND TO SENSO	RATING
Signature: Reviewed By: PE: Init: Date: / / Signature: Bridge #: COUNTY #70	WEST FORK ROAD BRIDGE OVER W. FORK CHANNEL 1ST W. OF MONTANA 3137104	6 P
Reviewed By: PE: Init: Date: // Signature: Bridge #: COUNTY #70	Inspected By: STEPHEN C. GRESSEL, P.E. PE:PE Init: SCG Dat	e:11/13/1996
Signature: Bridge #: COUNTY #70	Signature:	<del>4</del>
Bridge #: COUNTY #70	Reviewed By: PE: Init: Dat	e: / /
County: HAM Route: SO159 Unit: 0598 BrType (Main/Appr Spans): 171 / Year Built: 2800 Survey: 001111NN Needs to be Inventoried By: Load Rating Analyst Initials: Load Rating Analysis Date: // Inspection satisfies AASHTO Manual for Maintenance Inspection of Bridges "Routine Inspection" requirements. Not all main structural members were inspected within "arms reach" distance. File Location: 22-28-11 TO 24  1 FLOOR: Cracks, efforescence; spalling of gunite repairs; water saturation. 2  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only. 2  3 CURBS, SIDWLKSWLK WAYS: Cracks; spalls; extensive concrete deterioration. 2  5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel. 2  6 DRAINAGE: 2 Inlets with downspouts. 1  7 EXPANSION JCINTS: Leaking. 2  8 DECK SUMMARY: 6  9 STR ALIGNMENT: 1/4" to 1/2" lateral movement. 2  10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE. 2  31 LIVE LOAD RESPONSE: S  32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone. 6  33 ABUTMENTS: Moist; deteriorated, vertical cracks with efflorescence; spalling of gunite CONT 2  Substructure Notes BELOW: 3  34 ABUTMENT SEATS: Integral. 1  45 SUB SCOUR: Scour hole downstream approx. 8" deep. Type: 1  46 SUB SCOUR: Scour hole downstream approx. 8" deep. Type: 1  47 CHAALIGNMENT: 2	Signature:	
Survey: 001111NN Needs to be Inventoried By: Load Rating %: 75 Load Rating Analyst Initials: Load Rating Analysis Date: / / Inspection satisfies AASHTO Manual for Maintenance Inspection of Bridges "Routine Inspection" requirements. Not all main structural members were inspected within "arms reach" distance.  File Location: 22-28-11 TO 24  1 FLOOR: Cracks; efforescence; spalling of gunite repairs; water saturation.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  3 CURBS, SIDWLKSWLK WAYS: Cracks; spalls; extensive concrete deterioration.  4 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag, crack @ 1st N.E. panel.  5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag, crack @ 1st N.E. panel.  6 DRAINAGE: 2 Inlets with downspouts.  1 EXPANSION JOINTS: Leaking.  2 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 LIVE LOAD RESPONSE:  3 LIVE LOAD RESPONSE:  3 LIVE LOAD RESPONSE:  3 ABUTMENTS: Moist, deteriorated, vertical cracks with efforescence; spalling of gunite CON'T  2 Substructure Notes BELOW.  3 ABUTMENTS: Moist, deteriorated, vertical cracks with efforescence; spalling of gunite CON'T  2 Substructure Notes BELOW.  3 ABUTMENTS: Funal 1991; graffiti.  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  1 Type: 1 2  4 SUBSTRUCTURE SUMMARY:  6 CHAALIGNMENT:  5 CHAALIGNMENT:  6 CHAALIGNMENT:	, , , , , , , , , , , , , , , , , , , ,	
Load Rating %: 75 Load Rating Analyst Initials: Load Rating Analysis Date: 7/ Inspection satisfies AASHTO Manual for Maintenance Inspection of Bridges "Routine Inspection" requirements.  Not all main structural members were inspected within "arms reach" distance.  File Location: 22-28-11 TO 24  1 FLOOR: Cracks; efforescence; spalling of gunite repairs; water saturation. 2  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only. 2  3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 2  5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel. 2  6 DRAINAGE: 2 inlets with downspouts. 1  7 EXPANSION JOINTS: Leaking. 2  8 DECK SUMMARY: 6  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement. 2  10 BEAMS/GRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE. 2  31 LIVE LOAD RESPONSE: S  32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant, not fatigue prone. 6  33 ABUT MENTS: Moist, deteriorated; vertical cracks with efforescence; spalling of gunite CON'T 2  Substructure Notes BELOW 3  4 ABUT MENTS: Moist, deteriorated; vertical cracks with efforescence; spalling of gunite CON'T 2  Substructure Notes BELOW 3  4 ABUT MENTS: Moist, deteriorated; vertical cracks with efforescence; spalling of gunite CON'T 2  Substructure Notes BELOW 3  4 ABUT MENTS: Moist, deteriorated; vertical cracks with efforescence; spalling of gunite CON'T 2  Substructure Notes BELOW 3  4 ABUT MENTS: Moist, deteriorated; vertical cracks with efforescence; spalling of gunite CON'T 2  Substructure Notes BELOW 3  4 ABUT MENTS: Moist, deteriorated; vertical cracks with efforescence; spalling of gunite CON'T 2  Substructure Notes BELOW 3  5 WINGWALLS: T-wall 1991; graffit. 1  6 CHA.ALIGNMENT: 2		
Inspection satisfies AASHTO Manual for Maintenance Inspection of Bridges "Routine Inspection" requirements. Not all main structural members were inspected within "arms reach" distance.  File Location: 22-28-11 TO 24  1 FLOOR: Cracks; efflorescence; spalling of gunite repairs; water saturation.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete spalls on N. side only.  2 WEARING SURFACE: Concrete spalls on N. side only.  2 WEARIN		
Not all main structural members were inspected within "arms reach" distance. Filie Location: 22-28-11 TO 24  1 FLOOR: Cracks; efforescence; spalling of gunite repairs; water saturation.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration.  5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel.  6 DRAINAGE: 2 inlets with downspouts.  7 EXPANSION JOINTS: Leaking.  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 2  10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 3  2 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 Substructure Notes BELOW.  3 ABUTIMENTS: Moist; deteriorated; vertical cracks with efforescence; spalling of gunite CONT 2  Substructure Notes BELOW.  3 WINGWALLS: T-wall 1991; graffitl.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  1 7 Type: 1 2  2 2 2 3 SUBSTRUCTURE SUMMARY:  6 3 CHA.ALIGNMENT: 1/4" to 1/2" lateral mapprox. 8" deep.  7 Type: 1 2  8 CHA.ALIGNMENT: 1/4" to 1/2" lateral mapprox. 8" deep.  8 CHA.ALIGNMENT: 1/4" to 1/2" lateral mapprox. 8" deep.  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2 3 SUPERSTRUCTURE SUMMARY: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
1 FLOOR: Cracks; efforescence; spalling of gunite repairs; water saturation.  2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration.  5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel.  6 DRAINAGE: 2 inlets with downspouts.  7 EXPANSION JOINTS: Leaking.  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 2  10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 31 LIVE LOAD RESPONSE:  32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 3 ABUTMENTS: Moist, deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  2 Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  35 WINGWALLS: T-wall 1991; graffiti.  40 SUB:SCOUR: Scour hole downstream approx. 8" deep.  7 Type: 1  2 CHA.ALIGNMENT:  6 CHA.ALIGNMENT:	Not all main structural members were inspected within "arms reach" distance.	
2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only. 2 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 2 ARAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel. 3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 2 ARAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel. 3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration. 3 CURBS, SIDWLKS/WLK WAYS: Leaking. 3 CURBS, SIDWLKS, WLK WAYS: Leaking. 3 CURBS,		
2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.  3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration.  2 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel.  2 PARAISON JOINTS: Leaking.  3 DECK SUMMARY:  4 DECK SUMMARY:  5 DECK SUMMARY:  6 DECK SUMMARY:  6 DECK SUMMARY:  7 EXPANSION JOINTS: Leaking.  8 DECK SUMMARY:  8 DECK SUMMARY:  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 2 2 3 LIVE LOAD RESPONSE:  5 S 3 2 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 SUBSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  8 SUBSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  9 SUBSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  10 SUBSCOUR: Scour hole downstream approx. 8" deep.  11 Type: 1 2 2 3 SUBSTRUCTURE SUMMARY:  12 SUBSTRUCTURE SUMMARY:  13 CHAALIGNMENT:  5 CHAALIGNMENT:  14 CHAALIGNMENT:  5 CHAALIGNMENT:  2 SUBSTRUCTURE SUMMARY:  6 CHAALIGNMENT:  9 CARCHARY SURFACE  15 CHAALIGNMENT:  1 SUBSTRUCTURE SUMMARY:  1 SUBSTRU	TIPLOOK: Gracks; emorescence; spailing or gunite repairs; water saturation.	
3 CURBS, SIDWLKS/WLK WAYS: Cracks; spalls; extensive concrete deterioration.  2 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel.  5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel.  2 CARAINAGE: 2 inlets with downspouts.  1 PEXPANSION JOINTS: Leaking.  2 EXPANSION JOINTS: Leaking.  3 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 CARAINAGE: 2 inlets with downspouts.  4 DECK SUMMARY:  5 DECK SUMMARY:  6 CARAINAGE: 2 inlets with downspouts.  1 DECK SUMMARY:  6 CARAINAGE: 2 inlets with downspouts.  1 DECK SUMMARY:  2 DECK FLOOR, LINE 1 ABOVE.  2 DECK FLOOR, LINE 1 ABOVE.  2 DECK FLOOR, LINE 1 ABOVE.  3 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  4 DECK SUMMARY:  4 DECK SUMMARY:  5 DECK SUMMARY:  5 DECK SUMMARY:  5 DECK SUMMARY:  5 DECK SUMMARY:  6 DECK SUMMARY:  8 DECK SUMMARY:  8 DECK SUMMARY:  8 DECK SUMMARY:  9 STR.ALIGNMENT:  1 STR.ALIGNMENT:	2 WEARING SURFACE: Concrete overlay 1991; minor cracks. Concrete spalls on N. side only.	
5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel. 2 6 DRAINAGE: 2 inlets with downspouts. 1 7 EXPANSION JOINTS: Leaking. 2 8 DECK SUMMARY: 6 9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement. 2 10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE. 2 31 LIVE LOAD RESPONSE: 5 32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone. 6 33 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T 2 Substructure Notes BELOW 3 4 ABUTMENT SEATS: Integral. 1 40 SUB.SCOUR: Scour hole downstream approx. 8" deep. Type: 1 2 42 SUBSTRUCTURE SUMMARY: 6 51 CHA.ALIGNMENT: 2		
6 DRAINAGE: 2 inlets with downspouts.  7 EXPANSION JOINTS: Leaking.  8 DECK SUMMARY:  6 9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 2 10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2 11 LIVE LOAD RESPONSE:  S 3 2 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant, not fatigue prone.  6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 CURBS, SIDVVLKS/VVLK VVAYS: Gracks; spalls; extensive concrete deterioration.	2
6 DRAINAGE: 2 inlets with downspouts.  7 EXPANSION JOINTS: Leaking.  8 DECK SUMMARY:  6 9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 1  10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2  2 1 LIVE LOAD RESPONSE:  3 2 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 1  3 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CONT  2 Substructure Notes BELOW.  3 ABUTMENT SEATS: Integral.  3 WINGWALLS: T-wall 1991; graffit.  4 SUB-SCOUR: Scour hole downstream approx. 8" deep.  7 Type: 1  4 SUB-STRUCTURE SUMMARY:  6 CHA-ALIGNMENT:	5 RAILING: Concrete panel railing; vertical cracks at mid-panel points; diag. crack @ 1st N.E. panel	el. 2
7 EXPANSION JOINTS: Leaking.  2 8 DECK SUMMARY:  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2 31 LIVE LOAD RESPONSE:  3 2 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 3 ABUTMENTS: Moist, deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  2 Substructure Notes BELOW  3 ABUTMENT SEATS: Integral.  3 WINGWALLS: T-wall 1991; graffiti.  4 SUB-SCOUR: Scour hole downstream approx. 8" deep.  7 Type: 1 2  4 SUBSTRUCTURE SUMMARY:  6 CHA-ALIGNMENT:		
7 EXPANSION JOINTS: Leaking.  8 DECK SUMMARY:  6 1  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 1  10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2  31 LIVE LOAD RESPONSE:  S 32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 33 ABUTMENTS: Moist, deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  2 Substructure Notes BELOW:  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6 6  51 CHA.ALIGNMENT:  2 2	6 DRAINAGE: 2 inlets with downspouts.	1
8 DECK SUMMARY:  9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 2 10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 31 LIVE LOAD RESPONSE:  32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 3 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6 6  54 CHA.ALIGNMENT:  2 2	7 EXPANSION JOINTS: Leaking.	
9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 2 10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2 31 LIVE LOAD RESPONSE:  S 32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 33 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  2 Substructure Notes BELOW:  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6 1  6 1  6 1  6 1  6 1  6 1  6 1  6		
9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.  2 10 BEAMS/GIRDERS/SLAB: Slab structure; SEE DECK FLOOR, LINE 1 ABOVE.  2 2 31 LIVE LOAD RESPONSE:  3 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  6 Substructure Notes BELOW:  3 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  Substructure Notes BELOW:  3 ABUTMENT SEATS: Integral.  3 WINGWALLS: T-wall 1991; graffiti.  4 SUB.SCOUR: Scour hole downstream approx. 8" deep.  7 Type: 1 2  4 SUBSTRUCTURE SUMMARY:  6 CHA.ALIGNMENT:	8 DECK SUMMARY:	
31 LIVE LOAD RESPONSE:  32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  33 ABUTMENTS: Moist, deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  Substructure Notes BELOW.  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2	9 STR.ALIGNMENT: 1/4" to 1/2" lateral movement.	
31 LIVE LOAD RESPONSE:  32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  33 ABUTMENTS: Moist, deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  Substructure Notes BELOW.  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2	10 BEAMS/CIRDERS/SLAB: Slab structure: SEE DECK ELOOP, LINE 1 ABOVE	
32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  33 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	10 BEAMO, CIRDERO CONTROL CIRCUITA CONTROL FEORE FEORE, EINE TABOVE.	
32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16; redundant; not fatigue prone.  33 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  2 Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  7 Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6 SUBSTRUCTURE SUMMARY:  6 CHA.ALIGNMENT:	31 LIVE LOAD RESPONSE:	S
33 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T  Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  1 1  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2		
Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2	32 SUPERSTRUCTURE SUMMARY. Plans filed 22-28-13 to 16; redundant; not ratigue prone.	b l
Substructure Notes BELOW  34 ABUTMENT SEATS: Integral.  38 WINGWALLS: T-wall 1991; graffiti.  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2	33 ABUTMENTS: Moist; deteriorated; vertical cracks with efflorescence; spalling of gunite CON'T	2
38 WINGWALLS: T-wall 1991; graffiti.  40 SUB.SCOUR: Scour hole downstream approx. 8" deep.  Type: 1 2  42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2	Substructure Notes BELOW	
38 WINGWALLS: T-wall 1991; graffiti. 1 40 SUB.SCOUR: Scour hole downstream approx. 8" deep. Type: 1 2 42 SUBSTRUCTURE SUMMARY: 6 51 CHA.ALIGNMENT: 2	34 ABUTMENT SEATS: Integral.	300-0046
42 SUBSTRUCTURE SUMMARY: 6 51 CHA.ALIGNMENT: 2	38 WINGWALLS: T-wall 1991; graffiti.	1
42 SUBSTRUCTURE SUMMARY: 6 51 CHA.ALIGNMENT: 2	40 ISUB SCOUR: Scour hole downstroom approx. 8" doos	4
42 SUBSTRUCTURE SUMMARY:  6  51 CHA.ALIGNMENT:  2	To be seen the downstream approx. o deep.	
51 CHA.ALIGNMENT: 2	42   SUBSTRUCTURE SUMMARY:	
52 PROTECTION: Stream undercutting downstream; grout rock fill.	51   CHA.ALIGNMENT:	
	52 PROTECTION: Stream undercutting downstream: grout rock fill	7
・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・		

en Maria

WEST FORK ROAD BRIDGE OVER W. FORK CHANNEL 1ST W. OF MONTANA  3137104 6 P Inspected By: STEPHEN C. GRESSEL, P.E.  PE: PE Init: SCG Date: 11/13/1996 Signature:  Reviewed By:  PE: Init: Date: / /  Signature:  Bridge #: COUNTY #70 Insp Resp: COUNTY  Maint Resp: COUNTY  3 WATERWAY ADEQUACY: Highwater flow may be restricted by the bridge.  3 4 CHANNEL SUMMARY:  6 P Inspected By: STEPHEN C. GRESSEL, P.E.  PE: PE Init: SCG Date: 11/13/1996  Maint Resp: COUNTY  Maint Resp: COUNTY  53 WATERWAY ADEQUACY: Highwater flow may be restricted by the bridge.  54 CHANNEL SUMMARY:  6 P 13 55 PAVEMENT: Asphalt cracked & loose @ S.W. @ park entrance; patch near roadway.  2 2 56 APPROACH SLABS: Asphalt overlayed, not visible if present.  57 GUARDRAIL:  1 1 58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  2 2 60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge.  6 1 6 6 GEN/APPRAIS/OPERATIONS:  Condition: 6 P	BRIDGE IVA	MEZINSPECTIO	TIME SERVICE			AND SE	N BERA	TING
Signature:  Reviewed By: PE: Init: Date: / / Signature:  Bridge #: COUNTY #70 Insp Resp: COUNTY  53 WATERWAY ADEQUACY: Highwater flow may be restricted by the bridge. 3  54 CHANNEL SUMMARY: 6  55 PAVEMENT: Asphalt cracked & loose @ S.W. @ park entrance; patch near roadway. 2  56 APPROACH SLABS: Asphalt overlayed, not visible if present. 1  57 GUARDRAIL: 1  58 RELIEF JOINTS: None apparent. 2  60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge. 6  61 WARNING SIGNS: Posted 30 Tons. 1  65 VERTICAL CLEARANCE: N	WEST FORK	ROAD BRIDGE C	VER W. FORK CHANNE	L 1ST W. OF I	MONTAN	A 313	7104 6	Р
Reviewed By: PE: Init: Date: / / Signature:  Bridge #: COUNTY #70	Inspected By	STEPHEN C. GF	ESSEL, P.E.		PE:PE	Init: SCG	Date: 11/13/	1996
Signature:  Bridge #: COUNTY #70	Signature							
Bridge #: COUNTY #70 Insp Resp: COUNTY  53 WATERWAY ADEQUACY: Highwater flow may be restricted by the bridge.  3 SA CHANNEL SUMMARY:  54 CHANNEL SUMMARY:  55 PAVEMENT: Asphalt cracked & loose @ S.W. @ park entrance; patch near roadway.  2 SA APPROACH SLABS: Asphalt overlayed, not visible if present.  57 GUARDRAIL:  58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  2 SA APPROACHES SUMMARY: Sharp horiz, curves off both ends of bridge.  60 APPROACHES SUMMARY: Sharp horiz, curves off both ends of bridge.  61 WARNING SIGNS: Posted 30 Tons.  1 SA SECTION OF THE PROPERTY OF THE	Reviewed By	•			PE:	lnit:	Date: / /	
53 WATERWAY ADEQUACY: Highwater flow may be restricted by the bridge.  54 CHANNEL SUMMARY:  6 SECTION OF THE PROPERTY OF THE P	l <u></u>							
54 CHANNEL SUMMARY:  55 PAVEMENT: Asphalt cracked & loose @ S.W. @ park entrance; patch near roadway.  2 Separation of the property of the present of the pr	I					esp: COUN	ΓY	
55 PAVEMENT: Asphalt cracked & loose @ S.W. @ park entrance; patch near roadway.  2  56 APPROACH SLABS: Asphalt overlayed, not visible if present.  57 GUARDRAIL:  1 1  58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  2 2  60 APPROACHES SUMMARY: Sharp horiz, curves off both ends of bridge.  6 EQ WARNING SIGNS: Posted 30 Tons.  1 1  65 VERTICAL CLEARANCE:  N	53 WATERW	AY ADEQUACY: I	Highwater flow may be res	stricted by the b	oridge.			3
55 PAVEMENT: Asphalt cracked & loose @ S.W. @ park entrance; patch near roadway.  2  56 APPROACH SLABS: Asphalt overlayed, not visible if present.  57 GUARDRAIL:  1 1  58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  2 2  60 APPROACHES SUMMARY: Sharp horiz, curves off both ends of bridge.  6 EQ WARNING SIGNS: Posted 30 Tons.  1 1  65 VERTICAL CLEARANCE:  N	EA CHANNE	CHAMADV			All the second s			
56 APPROACH SLABS: Asphalt overlayed, not visible if present.  57 GUARDRAIL:  58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  50 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge.  60 WARNING SIGNS: Posted 30 Tons.  50 VERTICAL CLEARANCE:  50 N	34 CHANNE	L SUIVINART.		ing the large of the second	(Salah Salah)	tariopus (Sanatalina)	olegi <del>a di</del> visioner:	б
57 GUARDRAIL:  58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  20  60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 Tons.  11  65 VERTICAL CLEARANCE:  N	55  PAVEME	NT: Asphalt cracke	d & loose @ S.W. @ park	entrance; pate	h near ro	adway.	TO THE KONTENSION OF THE PARTY	2
57 GUARDRAIL:  58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  20  60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 Tons.  11  65 VERTICAL CLEARANCE:  N	EC ADDOO	CU CLADO, Assis		ing at an fig. out have solding.				
58 RELIEF JOINTS: None apparent.  59 EMBANKMENT: Very steep.  60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 Tons.  1 65 VERTICAL CLEARANCE:	56 APPROAG	on Stabs, Aspha	t overlayed, not visible it p	oresent.				ETPROPE I
59 EMBANKMENT: Very steep. 2  60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge. 6  62 WARNING SIGNS: Posted 30 Tons. 1  65 VERTICAL CLEARANCE: N	57 GUARDR	AIL:	eki 1980, 1981 (1986) ke ilangan Perentahan bahasah bahasan beraran 1984 y					1
59 EMBANKMENT: Very steep. 2  60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge. 6  62 WARNING SIGNS: Posted 30 Tons. 1  65 VERTICAL CLEARANCE: N					the company of the co			羅羅
60 APPROACHES SUMMARY: Sharp horiz. curves off both ends of bridge. 62 WARNING SIGNS: Posted 30 Tons. 1 65 VERTICAL CLEARANCE: N	36 KELIEF J	Olivio, None appa	rent. Modernia		arazi yareka			Signature 1
60 APPROACHES SUMMARY: Sharp horiz, curves off both ends of bridge. 62 WARNING SIGNS: Posted 30 Tons. 1 65 VERTICAL CLEARANCE: N	59 EMBANKI	MENT: Very steep	elimentip min massipropoliproportigen indication 144904				4.1.100.70.000.000.000.000	2
62 WARNING SIGNS: Posted 30 Tons.  65 VERTICAL CLEARANCE:  N					este da unição		ergijās enekā.	
65 VERTICAL CLEARANCE: N	60 APPROAC	CHES SUMMARY:	Sharp horiz, curves off bo	oth ends of brid	lge.	no gran organizacións des	et ura et et eteratura de et et et et et	6
65 VERTICAL CLEARANCE: N	62 WARNING	SIGNS: Posted 3	0 Tons.	- en				1
66 GEN/APPRAIS/OPERATIONS: Condition: 6 P	65 VERTICA	L CLEARANCE:						N
Condition: 6 P	SE GENIADD	RAIS/ODERATION	IS:	n - Frank de la serie de l La serie de la			Condition	
	JUD GLIWAPP	TAIS/OF ERATION		in in American, where he could be to			Condition:	01

## **Substructure Notes:**

ABUTMENTS: repairs; S.W. & S.E. abutments offset @ wingwall, possible movement of 1/4" to 1/2"...

## Maintenance Items:

- 1) Seal cracks in wearing surface and approach slab with HMWM.
- 2) Remove debris from walks and curbs.
- 3) Remove vines growing on bridge.
- 4) Remove vegetation growing thru T-wall joints.
- 5) Place dump rock fill on downstream side where strambed is cutting under grouted fill in front of T-walls.

## Inspection Notes:

NOTE: Seepage at S.E. embankment.

BRIDGE NAME / INSPECTION ITEMS	SFN MERATING
WEST FORK ROAD BRIDGE OVER W. FORK CHANNEL 2ND W. OF MONTANA	3136329 5 P
Inspected By: STEPHEN C. GRESSEL, P.E. PE:PE Init: So	CG Date: 11/13/1996
Signature:	
Reviewed By: PE: Init:	Date: / /
Signature:	
Bridge #: COUNTY #71 Insp Resp: COUNTY Maint Resp: CO	DUNTY
County: HAM Route: SO159 Unit: 0589 BrType (Main/Appr Spans): 171 /	
Survey: 001111NN Needs to be Inv	
Load Rating %: 75 Load Rating Analyst Initials: Load Rating Analysis	
Inspection satisfies AASHTO Manual for Maintenance Inspection of Bridges "Routine Inspe	ection" requirements.
Not all main structural members were inspected within "arms reach" distance.  File Location: 22-28-11 TO 24	
1 FLOOR: Water saturation; extensive cracking; efflorescence; concrete deterioration; gu	
2 WEARING SURFACE: Cracks; most formerly sealed, however worn, offset, and displa	iced; deck 2
CONT Deck Notes BELOW	ceu, ueck 2
3 CURBS, SIDWLKS/WLK WAYS: Transverse cracks; debris at curbs.	2
5 RAILING: Concrete panel railing, vertical cracks at mid panel points.	2
	realistication to the second
6 DRAINAGE: 4 inlets without downspouts (on east side only), all open; one downspout	broken. 2
7 EXPANSION JOINTS: Joints closed, leaking; formerly sealed.	3
8 DECK SUMMARY:	5
9 STR.ALIGNMENT: Minor settlement off bridge.	2
10 BEAMS/GIRDERS/SLAB: Seepage, cracks, efflor. of concrete encasement at center s	CONT
Superstructure Notes BELOW	pan; CON'T 3
11 DIAPHRAGMS/CROSSFRAMES: Seepage, cracks & efflorescence; part. at N. face of	S. pier; CON'T 3
Superstructure Notes BELOW	<b>43</b>
24 BEARING DEVICES: Seepage; deterioration; gunite repairs; bearings for center span	
31 LIVE LOAD RESPONSE:	S
32 SUPERSTRUCTURE SUMMARY: Plans filed 22-28-13 to 16, redundant-not fatigue pro	one. 5
33 ABUTMENTS: Cracks; seepage; efflor.; lg. (app.1/2") full length vert. crack @ NW; CC	ON'T Substructure 3
Notes BELOW	
34 ABUTMENT SEATS: Integral.	
35 PIERS: Cracks; efflorescence; full length vertical crack at N. face of N. pier and CON'T Notes: BELOW	Substructure 2
INDICATIONAL SERVICE S	

59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 tons.	BRIDGE NAME / INSPECTION			<b>一种,我们就是一种,他们也可以把这种的时间,但是一个</b>	N See F	ATING
Signature:  Reviewed By: PE: Init: Date: / / Signature:  Bridge #: COUNTY #71 Insp Resp:COUNTY  36   PIER SEATS: At center span only; seepage; efflorescence; deterioration; gunite repairs. 2  38   WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence. 3  40   SUB.SCOUR: Scour corrected with grouted concrete rip-rap. Type: 1   2  42   SUBSTRUCTURE SUMMARY:   5  51   CHA.ALIGNMENT:   1  52   PROTECTION: Grouted concrete rip-rap protection at channel floor, erosion; concrete deterioration. 2  53   WATERWAY ADEQUACY: Bridge may restrict flow at extreme highwater.   2  54   CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion.   5  55   PAVEMENT: Repaved 1991; transverse cracks at S.   1  56   APPROACH SLABS: Asphalt overlayed; not visible (if provided).   1  57   GUARDRAIL: Replaced 1991.   1  58   EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.   3  69   APPROACHES SUMMARY: Sharp horizonal curves of both ends of bridge.   6  60   WARNING SIGNS: Posted 30 tons.   1  61   VERTICAL CLEARANCE:   N  62   VERTICAL CLEARANCE:   N  63   GEN/APPRAIS/OPERATIONS:   Condition:   5 P	WEST FORK ROAD BRIDGE OVE	R W. FORK CHANNEL 21	ND W. OF MONTAN	A 313	6329	5 P
Reviewed By: PE: Init: Date: / / Signature:  Bridge #: COUNTY #71		SSEL, P.E.	PE:PE	Init: SCG	Date: 11/	13/1996
Signature:  Bridge #: COUNTY #71						
Bridge #: COUNTY #71 Insp Resp: COUNTY  36   PIER SEATS: At center span only; seepage; efflorescence; deterioration; gunite repairs. 2  38   WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence. 3  40   SUB.SCOUR: Scour corrected with grouted concrete rip-rap. Type: 1   2  42   SUBSTRUCTURE SUMMARY: 5  51   CHA.ALIGNMENT: 5  52   PROTECTION: Grouted concrete rip-rap protection at channel floor, erosion; concrete deterioration. 2  53   WATERWAY ADEQUACY: Bridge may restrict flow at extreme highwater. 2  54   CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion. 5  55   PAVEMENT: Repawed 1991; transverse cracks at S. 1  56   APPROACH SLABS: Asphalt overlayed; not visible (if provided). 5  57   GUARDRAIL: Replaced 1991. 1  58   EMBANKMENT: Extensive erosion at all four corners of bridge; very steep. 3  60   APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge. 6  61   VERTICAL CLEARANCE:	Reviewed By:		PE:	Init:	Date: /	/
36 PIER SEATS: At center span only; seepage; efflorescence; deterioration; gunite repairs.  2 38 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 38 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 38 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 38 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 38 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 40 SUB.SCOUR: Scour corrected with grouted concrete rip-rap.  5 51 CHA.ALIGNMENT:  5 52 PROTECTION: Grouted concrete rip-rap protection at channel floor; erosion; concrete deterioration.  2 52 PROTECTION: Grouted concrete rip-rap protection at channel floor; erosion; concrete deterioration.  2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				·		<del></del>
38 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  5 Condition: 3 WINGWALLS: Numerous cracks due to differential settlement w/ minor efflorescence.  5 Condition: 3 WINGWALLS: Numerous corrected due to differential settlement w/ minor efflorescence.  5 Condition: 3 WINGWALLS: Numerous corrected with grouted concrete rip-rap.  5 WALLS: Numerous corrected with grouted concrete rip-rap.  5 Condition: 3 WINGWALLS: Numerous corrected due to differential settlement w/ minor efflorescence.  5 VERTICAL CLEARANCE: Numerous corrected due to differential settlement w/ minor efflorescence.  5 VERTICAL CLEARANCE: Numerous corrected due to differential settlement w/ minor efflorescence.  5 VERTICAL CLEARANCE: Numerous corrected due to differential settlement w/ minor efflorescence.  5 VERTICAL CLEARANCE: Numerous corrected due to differential settlement w/ minor due to differential settlement					ΓY	-
40 SUB.SCOUR: Scour corrected with grouted concrete rip-rap.  7 Type: 1 2  42 SUBSTRUCTURE SUMMARY: 5  51 CHA.ALIGNMENT: 1  52 PROTECTION: Grouted concrete rip-rap protection at channel floor, erosion; concrete deterioration. 2  53 WATERWAY ADEQUACY: Bridge may restrict flow at extreme highwater. 2  54 CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion. 5  55 PAVEMENT: Repaved 1991; transverse cracks at S. 1  56 APPROACH SLABS: Asphalt overlayed; not visible (if provided). 1  57 GUARDRAIL: Replaced 1991. 1  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep. 3  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge. 6  62 WARNING SIGNS: Posted 30 tons. 1  65 VERTICAL CLEARANCE: N  66 GEN/APPRAIS/OPERATIONS: Condition: 5 P	36 PIER SEATS: At center span o	nly; seepage; efflorescence	e; deterioration; gunite	e repairs.		2
42 SUBSTRUCTURE SUMMARY:  5	38 WINGWALLS: Numerous crack	s due to differential settlen	ent w/ minor efflores	cence.		3
51 CHA.ALIGNMENT:  52 PROTECTION: Grouted concrete rip-rap protection at channel floor, erosion; concrete deterioration.  53 WATERWAY ADEQUACY: Bridge may restrict flow at extreme highwater.  54 CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion.  55 PAVEMENT: Repaved 1991; transverse cracks at S.  11  56 APPROACH SLABS: Asphalt overlayed; not visible (if provided).  57 GUARDRAIL: Replaced 1991.  1 1  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  3  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 tons.  1 65 VERTICAL CLEARANCE:  N 66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	40 SUB.SCOUR: Scour corrected	with grouted concrete rip-ra	ip.		Type:	1 2
51 CHA.ALIGNMENT:  52 PROTECTION: Grouted concrete rip-rap protection at channel floor, erosion; concrete deterioration.  53 WATERWAY ADEQUACY: Bridge may restrict flow at extreme highwater.  54 CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion.  55 PAVEMENT: Repaved 1991; transverse cracks at S.  1 1  56 APPROACH SLABS: Asphalt overlayed; not visible (if provided).  57 GUARDRAIL: Replaced 1991.  1 2 3 4 5 5 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  3 6 6 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  6 6 VERTICAL CLEARANCE:  N 6 6 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	42 SUBSTRUCTURE SUMMARY					
WATERWAY ADEQUACY: Bridge may restrict flow at extreme highwater.  2 54 CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion.  55 PAVEMENT: Repaved 1991; transverse cracks at S.  1 56 APPROACH SLABS: Asphalt overlayed; not visible (if provided).  57 GUARDRAIL: Replaced 1991.  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  3 60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  6 WARNING SIGNS: Posted 30 tons.  1 65 VERTICAL CLEARANCE:  N 66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	51 CHA.ALIGNMENT:				A service of the serv	1
54 CHANNEL SUMMARY: SMU is letting channel revert to its natural state; extensive slope erosion.  55 PAVEMENT: Repaved 1991; transverse cracks at S.  1 1  56 APPROACH SLABS: Asphalt overlayed; not visible (if provided).  57 GUARDRAIL: Replaced 1991.  1 1  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  3 0  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  6 1  62 WARNING SIGNS: Posted 30 tons.  1 1  65 VERTICAL CLEARANCE:  N 66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	52 PROTECTION: Grouted concre	ete rip-rap protection at cha	nnel floor; erosion; co	oncrete dete	rioration.	2
55 PAVEMENT: Repaved 1991; transverse cracks at S. 1  56 APPROACH SLABS: Asphalt overlayed; not visible (if provided).  57 GUARDRAIL: Replaced 1991. 1  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep. 3  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge. 6  62 WARNING SIGNS: Posted 30 tons. 1  65 VERTICAL CLEARANCE: N  66 GEN/APPRAIS/OPERATIONS: Condition: 5 P	53 WATERWAY ADEQUACY: Brid	lge may restrict flow at extr	eme highwater.			2
56 APPROACH SLABS: Asphalt overlayed; not visible (if provided).  57 GUARDRAIL: Replaced 1991.  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  3 60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 tons.  1 65 VERTICAL CLEARANCE:  N 66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	54 CHANNEL SUMMARY: SMU is	letting channel revert to its	natural state; extens	ive slope er	osion.	5
57 GUARDRAIL: Replaced 1991.  59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 tons.  10 65 VERTICAL CLEARANCE:  N 66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	55 PAVEMENT: Repaved 1991; tr	ansverse cracks at S.				1
59 EMBANKMENT: Extensive erosion at all four corners of bridge; very steep.  60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 tons.  65 VERTICAL CLEARANCE:  66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	56 APPROACH SLABS: Asphalt o	verlayed; not visible (if prov	ided).			
60 APPROACHES SUMMARY: Sharp horizonal curves off both ends of bridge.  62 WARNING SIGNS: Posted 30 tons.  65 VERTICAL CLEARANCE:  86 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	57 GUARDRAIL: Replaced 1991.					1
62 WARNING SIGNS: Posted 30 tons.  65 VERTICAL CLEARANCE:  N  66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P	59 EMBANKMENT: Extensive eros	sion at all four corners of br	dge; very steep.		January Logical Common Law	3
62 WARNING SIGNS: Posted 30 tons.  65 VERTICAL CLEARANCE:  N  66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P		arp horizonal curves off bo	th ends of bridge.			{
65 VERTICAL CLEARANCE:  N  66 GEN/APPRAIS/OPERATIONS:  Condition: 5 P		ons.				
66 GEN/APPRAIS/OPERATIONS: Condition:   5 P	65 VERTICAL CLEARANCE:					
Soliditon: 61	66 GEN/APPRAIS/OPERATIONS		Arter (1900) - Make Albert (1904) Albert (1904) Arter (1904) - Make Albert (1904) Albert (1904) Arter (1904) - Make Albert (1904) Albert (1904)			
				THE CHARLES	Conditio	, ,

## Deck Notes:

WEARING SURFACE CON'T: overlay (1986) with extensive shrinkage cracks; longitudinal crack concrete at center line with spalls.

## Superstructure Notes:

BEAMS/GIRDERS/SLAB CON'T: gunite repairs with efflorescence; shrinkage cracks:

DIAPHRAGMS/CROSSERAMES CONT::gunite:repairs; some cracks; are diagonal.:

Bridge #: COUNTY #71	Insp Resp: COUNTY	Maint Ro	sp: COUN	TY	
Signature:					
Reviewed By:	***	PE:	lnit:	Date: / /	
Signature:					
Inspected By: STEPHEN C.	GRESSEL, P.E.	PE:PE	Init: SCG	Date: 11/1:	3/1996
	E OVER W. FORK CHANNEL 2ND \	W. OF MONTAN	4 313	36329	5 P
BRIDGE NAME / INSPECT	IONITED - TOTAL PLANT		SI	NEWR	ATING

### Substructure Notes:

ABUTMENTS CON'T: gunite spalls @ E.; apparent offset @ crack approx. 3/8"; N.W. abutment offset 1" to 2".

PIERS CONT: S. face of S. pier, minor spalls; former gunite repairs; excessive soil and rock buildup at W. corner of S. pier, and E. corner of N. pier.

## General Notes:

Preliminary work on plans for a replacement bridge on new alignment.

## Maintenance Items:

1) Repair broken downspout

## ADDITIONAL SUPPORT INFORMATION

For Program Year 1997 (July 1, 1995 through June 30, 1998), jurisdictions shall provide the following support information to help determine which projects will be funded. Information on this form must be accurate, and where called for, based on sound engineering principles. Documentation to substantiate the individual items may be required by the Support Staff if information does not appear to be accurate.

1) What is the condition of the existing infrastructure to be replaced,

_	paired, or expanded? For bridges, submit a copy of the current State
	Closed Poor X
	Fair Good
	Give a brief statement of the nature of the deficiency of the present facility such as: inadequate load capacity (bridge); surface type and width; number of lanes; structural condition; substandard design elements such as berm width, grades, curves, sight distances, drainage structures, or inadequate service capacity. If known, give the approximate age of the infrastructure to be replaced, repaired, or expanded.
	Please see attached sheet.
2)	If State Issue 2 funds are awarded, how soon (in weeks or months) after receiving the Project Agreement from OPWC (tentatively set for July 1, 1997) would the project be under contract? The Support Staff will be reviewing status reports of previous projects to help judge the accuracy of a particular jurisdiction's anticipated project schedule.
	3 months
	Are preliminary plans or engineering completed? <u>No</u>
	Are detailed construction plans completed? <u>No</u>
	Are all right-of-way and easements acquired?* No
	* Please answer the following if applicable:
	No. of parcels needed for project: 2 . Of these, how many are Takes 2 , Temporary 0 , Permanent 0 .
	On a separate sheet, explain the status of the ROW acquisition process of this project for any parcels not yet acquired.
	Are all utility coordinations completed? No
	Give an estimate of time, in weeks or months, to complete any item above not yet completed. 9 Months

3)	How will the proposed project impact the general health, safety and welfare of the service area? (Typical examples may include the effects of the completed project on accident rates, emergency response time, fire protection, health hazards, user benefits, and commerce.) Please be specific and provide documentation if necessary to substantiate the data.
	Safety hazards due to poor roadway alignment, very limited sight
	distances around bridges and restricted lane widths. Pedestrian safety
	hazards for the public picnic area adjacent to the project. Severe
	undermining of the north bridge's piers poses a future threat to the
	safety of the north bridge. Both bridges are currently posted for a
	maximum of 30 tons.
4)	What type of funds are to be utilized for the local share for this project?
	Federal ODOT Local X
	MRF OWDA CD
	Other
	Note: If MRF funds are being used for the local share, the MRF application must have been filed by August 1, 1993 for this project with the Hamilton County Engineer's Office.
	The minimum amount of matching funds for grant projects (local share) must be at least 10% of the TOTAL CONSTRUCTION COST. What percentage of matching funds are being committed to this project?  30 %
5)	Has any formal action by a federal, state, or local government agency resulted in a complete or partial ban of the use or expansion of use for the involved infrastructure? (Typical examples include weight limits, truck restrictions, and moratoriums or limitations on issuance of building permits.) A copy of the legislation must be submitted with the application. THE BAN MUST HAVE AN ENGINEERING JUSTIFICATION TO BE VALID.
	Complete Ban Partial Ban X (30 tons) No Ban
	Will the ban be removed after the project is completed?
	Yes X No

0)	result of the proposed project?
	5502
	For roads and bridges, multiply current <u>documented</u> Average Daily Traffic by 1.20. For public transit, submit documentation substantiating the count. Where the facility currently has any restrictions or is partially closed, use documented traffic counts prior to the restriction. For storm sewers, sanitary sewers, water lines, and other related facilities, multiply the number of households in the service area by 4.
7)	Has the jurisdiction developed a Five Year Capital Improvement Plan as required in O.R.C., chapter 164?
	Yes X No
8)	Give a brief statement concerning the regional significance of the infrastructure to be replaced, repaired, or expanded.
	West Fork Road is the primary alternate route for Colerain Avenue. West Fork Road also provides access to numerous Mt. Airy Forest recreation areas, and is a designated bicycle route.
9)	For expansion projects, please provide the existing and proposed Level of Service (LOS) of the facility using the methodology outlined within AASHTO's Geometric Design of Highways and Streets, and the 1985 Highway capacity Manual.
	Existing LOS Proposed LOS
	If the proposed LOS is not C or better, explain why LOS C cannot be achieved. (Attach separate sheets if necessary.)

## WEST FORK ROAD: SAFETY UPGRADE AND BRIDGE REPLACEMENTS

#### 1.)

- a.) Currently, the existing horizontal bridge and roadway alignment severely restrict sight distance for vehicular traffic and pedestrians using the adjacent park facilities. Over the past year there have been 5 accidents attributed to the poor alignment (2 with serious injury). The proposed bridges and roadway will replace the hazardous compound curvature with a safer single curve for improved safety.
- b.) The roadway lane widths will be increased from 11.0' (existing) to 14.0'.
- c.) Both of the proposed bridges will include concrete channel protection to remove the threat of scour from the highly aggressive flow of the creeks below.
- d.) Removal of the existing bridge piers in the creek below the north bridge will reduce bridge maintenance costs and remove the threat of scour.
- e.) Since 1985 the two 70 year old bridges have been posted for a maximum capacity of 30 tons. Construction of the two proposed bridges will eliminate the current load restriction.
- f.) ODOT currently has both bridges rated as Functionally Obsolete.
  The South bridge has a Sufficiency Rating of 58.9, and the North
  Bridge has a Sufficiency Rating of 66.5.

Ç

2.) The City is currently acquiring two partial takes (10 ft. strips along West Fork Road) of property for widening of the existing roadway.

N BRIDGE PPROFICE KFROM SOUTH)



I LYOZ

CITY OF CINCLE ACTOR OF DEPARTMENT OF PUBLIC FRIGHTS OF TRAFFIC FRIGHTS OF TRAFFIC FRIGHTS OF TRAFFIC FRICHES OF TRAFFIC FRICHES

Mate 9-4-97 pproved

			Tr	affic Pro	o je kaje ne di	HEARD & SE	XIII	· ·
Roadwa	y WE	ST FOR	K RD		SION	AL-ENGINE		
From _	MOLITA	NA-		· .	To S	EPHERD=	u <del>ir</del>	
I. <u>Ex</u>	isting T	raffic Da	ta.				•	· · · · · · · · · · · · · · · · · · ·
·C	ount No.	92-0105	_ Date	4-14-92	Duration	24 hr	Volume	2387
C	ount No.	92-010-	4 Date	h	Duration	, h	Volume	2198
C	ount No.		Date _	· · · · · · · · · · · · · · · · · · ·	Duration		Volume	
	·				Existing	ADT = ·	4	585
	•		Peak Ho	our Highe	st Volume		,	
(EI	or NB .		5-6.		A.M. or	(P.M)	1.0	07
[VI	B)or SB	· · · · · · · · · · · · · · · · · · ·	5- <u>4</u>		A.M. or	P.M	.36	9
Ex	xisting ]	highest h	ourly vo	lume = _			47	6
. K.	= Design	n hour %	of ADT	. =		•		10.4%
D	= Design	n hour % ]	predomin	ate dire	ction =			<u>77.5</u> \$
Tr	ruck (B 8	& C) Bus 1	Route _	· H0	=	•	• •	& ;
· Tr	ruck Teri	rain Facto	or .		=	· ·	2	
II. <u>Des</u>	ign Year	Calcula	tion					
De	sign Yea	ır	2017	· = (	expansion	factor of		1.4
De	sign Yea	er ADT (No	ormal Gr	owth) =		•	641	9
De	sign Yea	er ADT (Ge	enerated	by plan	ned develo	pment)		· ·
Ďe	sign Yea	r (B & C)	Trucks	= 2	· % = ·		128	3
De	sign Yea	r (P & A)	<b>::</b> .		=		6291	
Т	= Design	Year Adj	. (B &	c) x <u>2</u>		· · · · · · · · · · · · · · · · · · ·	254	
					Design Y	ear ADT =	65	4-7
III. <u>Des</u>	ign Year	Hourly V	olume		•			
De	sign hou	r <u>5-6</u>	_ A.M.	or(P.M) -	- % ADT			.10.4 8
		•			nate direct	tion ·		77.5 %
					Design Ho	ourly Volu	ıme =	681
				Design	Directiona	al Hourly	Volume	528

## CITY OF CINCINNATI TRAFFIC ENGINEERING DIVISION

STREET(S): FROM W ON WEST FORK RD

LOCATION : E OF SHEPHERD RD

DIRECTION : EASTBOUND MAP COORDINATE: 255

DAY(S) OF WEEK: TUESDAY
WEATHER: CLORDY FO COMPUTER FILE NAME:

MACHINE NUMBER : 1923

TABULATED BY : TERRY/KEVIN 92-0104

STARTING TIME : 1:00 PM COMMENTS: 0 ADT FACTOR: 1.035

ONE-HOUR PERIOD	15 MIN.	PERIOD	STA	ARTING	ONE-HOUR PERIOD	PERCENT OF	
STARTING	:00	:15	:30	:45	TOTALS	TOTAL	
DNIINAIG	. 00	. 15	. 50	.43	io iala	TOTAL	· · ·
12A	1	6	2	4	13	0.61	
1A	4	1	O	2	7	0.33	•
2A	. 0	2	2	4	8	0.38	. 600
ЗА		0	1	4	. 7	0.33	· .
4 A	2 1	0	1	2	4	0.19	
5A	3	5	7	11	26	1.22	•
6A	15	22	35	38	110	5 - 18	
7 A		82	140	97	372	17.51	100
8A	77	69	52	√ 36	234	11.02	1.5
9A	25	19	19	21	84	3.95	
10A	15	22	24	18	79	3.72	
11A	18	21	16	27	82	3.86	
12P	17	32	24	39	112	5.27	
<b>1</b> P	25	24	26	22	97	4.57	
2P	34	18	33	17	102	4.80	
3 P	23	23	26	25	97	4.57	
4 P	28	30	29	24	111	5.23	
5P ·	3 1	24	21	3 1	(107)	5.04	
6P	36	36	33	28	133	6.26	
7 P	28	24	39	21	112	5.27	
8P	25	19	18	17	79	3.72	
9P	18	24	14	13	69	3.25	
10P	15	11	5	10	4 1	1.93	
1 1 P	11	11	12	4	38	1.79	
	тс	TAL 24	HOUR		2124	2198	= ADT
FIVE HOUR (7-9 AM &		921	24/5	FACTOR	2.3062		. •
EIGHT HOUS (7-11 AM 8			24/8	FACTOR	1.7909		

AM PEAK HOUR VOLUME IS 396 FROM 7:15 AM TO 8:15 AM PM PEAK HOUR VOLUME IS 136 FROM 5:45 PM TO 6:45 PM

TWELVE HOUR TOTAL 1587 24/12 FACTOR 1.3384

The secretary of the secretary of the secretary of the secretary secretary of the secretary secretary of the secretary secretary of the secretary secretary

(6:00 AM TO 6:00 PM)

## CITY OF CINCINNATI TRAFFIC ENGINEERING DIVISION

STREET(S): LOCATION :

FROM E ON WEST FORK RD

E OF SHEPHERD RD

DIRECTION : MAP COORDINATE:

WESTBOUND 255

APRIL 14,1992

DAY(S) OF WEEK : WEATHER:

TUESDAY CLOUDY 50

COMPUTER

MACHINE NUMBER :

DATE(S):

1923

FILE NAME:

TABULATED BY:

TERRY/KEVIN

92-0105

STARTING TIME :

1:00 PM

COMMENTS :	0
ADT FACTOR:	1.035

ONE-HOUR PERIOD	15 MIN.	PERIOD	ST	ARTING	ONE-HOUR	PERCENT	
STARTING	:00	:15	:30	: 45	PERIOD TOTALS	OF TOTAL	
12A	5	5	5	5	20	0.87	7
1A	1	3	9	3	16	0.69	
2A	5	3	1	1	10	0.43	•
3 Å	2	0	. 2	1	5	0.22	•
4 A	1	2	0	. 1	. 4	0.17	
5A	1	3	3	. 0	7	0.30	
6A	6	5	6	. 6	23	1.00	
7.A	11	17	17	14	59	2.56	
8A	12	25	10	20	67	2.91	
9 A	15	16	21	23	75	3 - 25	
10A	18	20	23	23	84	3.64	
1 1 A	12	22	35	3 1	100	4.34	
12P	39	3 1	32	30	132	5.72	
1 P	19	32	27	28	106	4.60	
2P	32	36	28	4 1	137	5.94	
3 b	3 7	43	44	58	182	7.89	
4 P	54	86	75	68	283	12.27	
5P	95	105	88	81	369	16.00	
6P	49	55	41	35	180	7.81	
7 P	34	27	28	32	121	5.25	
8 P	26	26	28	30	110	4.77	
9 P	3 3	20	20	28	101	4.38	
10P	17	26	14	14	7 1	3.08	
1 1 P	17	, 10	7	10	44	1.91	
	то	TAL 24 H	HOUR		2306	2387 =	ADT
FIVE HOUR (7-9 AM &		960 2	24/5	FACTOR	2.4021	. `	
EIGHT HOUR (7-11 AM &		1256 2	24/8	FACTOR	1.8360		

TWELVE HOUR TOTAL 1617 24/12 FACTOR 1.4261 (6:00 AM TO 6:00 PM)

AM PEAK HOUR VOLUME IS 127 FROM 11:15 AM TO 12:15 PM PM PEAK HOUR VOLUME IS 369 FROM 5:00 PM TO 6:00 PM

# 613

# TRAFFIC ENGINEERING ACCIDENT TRACKING SYSTEM ALL ACCIDENTS FROM 010196 TO 123196 DIVISION OF TRAFFIC ENGINEERING CITY OF CINCINNATI

COLL DIAG 3555 7333 57.27 37.77 7373 3731 5151 7333 7373 7373 3573 7333 3773 +1555 1555 5111 3777 1573 1511 7177 7333 5137 37 2 37 37 37 15 PROGRAM: TRFR1000 FIXED OBJ PARKED/VH PARKED/VH PARKED/VH FIXED OBJ ARKED/VH FIXED OBJ FIXED OBJ OTHER OBJ FIXED OBJ OTHER OBJ SW/MEET, ARKED/VH ARKED/VH ARKED/VH ARKED/VH TYPE OF REAR END REAR END CRASH SW/PASS SH/PASS REAR END SW/PASS SH/PASS SW/PASS BACKING ANIMAL ANGLE NGLE ROAD ᄶ DRY ZK. Z. DRY JRY. SXO PR PR В DRY DRY Ή DRY ያ Z.¥ )RY 7K√ ---CONDITIONS---LIGHT WEATHER CLEAR RAIN SKOH RAIN RAIN RAIN D/LT DUSK D/LT DUSK D/LT アゴ D/LT 건 DAY DAY DAY DΑY λ¥ λAΥ DAY DAY DNO DAY λ¥ λ¥ SPEED OR PED AGE 모 20 8 8 8 8 ĸ 8 53 7 30 8 8 8 8 N 8 8 8 23 20 8 皇 33 8 8 30 9 8 Ю S 5 8 30 45 33 8 8 2 8 Ж MID SIZE PANELVAN HID SIZE FULLSIZE MID SIZE MID SIZE MID SIZE PANELVAN FULLSIZE **MID SIZE** UNIT 2 FULLSIZE HID SIZE MID SIZE FULLSIZE PANELVAN FULLSIZE MID SIZE MID SIZE IME PREPARED: 10:46.25 SCH BUS BICYCLE **NENSKN** COMPACT PICKUP TYPE VEHICLE PED FULLSTZE MID SIZE MID SIZE MID SIZE UNIT 1 ULLS12E PANELVAN MID SIZE PANELVAN MID SIZE MID SIZE FULLSIZE PANELVAN CONST EQ MID SIZE FULLSTZE AID SIZE PICKUP COMPACT PICKUP M350CC COMPACT JIKNOHN NKNOMN NKNOMN NKNONN PICKUP PICKUP ) I CKUP PICKUP PICKUP UNIT 2 OTH D ER UNKNOWN UNKNOMN -----CAUSE----NOK 불 NONE NON NONE NONE HONE 잃 묖 뿔 NONE 몽오 NONE NON. 왕 **YONE** 왕 묏 몽 NONE NONE OST CNT V LOST CNT OST CNT OST CNT/ LOST CNT **FAILGATE TAILGATE** TAILGATE FAIL YLD SPEEDING LFT CENT D OFF RD MP TURN LOST CNT OTH D ER IMP STAR LOST CNT LOST CNT FAIL YLD UNIT 1 DR INATT OST CAT OST CNT OTH D ER MP BACK MP BACK OTH D ER LOST CNT OFF RD CHG LNS OST CNT NIMAL SP IN TRF SP IN TRF N SIDEWK STRAIGHT STRAIGHT STRAIGHT SP TO TN UNIT 2 STRAIGHT F TURN STRAIGHT STRAIGHT STRAIGHT UNKNOWN ARKED PARKED PARKED PARKED PARKED PARKED PARKED PARKED PARKED ARKED PARKED DR-PED-ACTION DATE PREPARED: 08/17/97 DTH D ACT ORIVERLES STRAIGHT LOST CNT LOST CNT STRAIGHT LOST CNT STRAIGHT UNIT 1 STRAIGHT STRAIGHT STRAIGHT STRAIGHT STRAIGHT STRA I GHT LOST CNT STRAIGHT STRA I GHT STRAIGHT STRAIGHT LOST CNT STRAIGHT DST CNT STRAIGHT LOST CNT SWERVING UN/PARK PASSING LF TURN BACKING BACKING U TURN SERIOUS SERIOUS INJURY DEGREE N/VIS MINGR MINOR MINOR NON NONE NONE NONE NON NONE 꽃 NONE NONE NONE YI NOR MINGR NONE NONE NONE 뽕오 몽옷 몽옷 봉양 불무 E E ACC 19 2 22 20 18 2 1, 5 8 13 능 DATE 1018 0720 0509 0426 0309 0229 1202 0904 1015 0804 0727 0224 0322 0919 0112 0211 0611 1013 0403 1006 0413 0217 0121 1026 1113 9090 1011 0111 NUMBER 4732 3126 8040 3679 7283 12334 7289 4510 3920 3118 17461 0304 2684 5291 0255 7196 5975 5579 6760 6498 6988 823 3351 7990 9224 9878 **111187111** 17791//// ICCIDENT LOCATION 1////0091 1836//// 1840//// 1868//// 2087//// 3076//// ////oo\*x 1540//// 1888//// 1896//// 1///0061 ///X5080 1891//// 1902//// 1910//// 2001//// 3420//// 3168//// 2080//// 2100//// 2149//// 2600//// 2651//// 5015//// 3373//// 3459//// 3461//// 3619//// 07\8/// ESCRIPTION OF EPORT#: 1000 )FORK/R /FORK/R /HIGH/A / /FORK/R KILLVA/ I/PORK/R I/FORK/R //FORK/R /FORK/R /FORK/R /FORK/R /FORK/R /FORK/R /FORK/R /FORK/R /FORK/R /FORK/R / FORK/R /FORK/R ABAÉH/A ABASH/A ADE/ST/ ATE/ST/ AbE/ST/ /HXTTAW /HILLY /IOME// **18.** €

# SCIP/LTIP PROGRAM ROUND 12 - PROGRAM YEAR 1998 PROJECT SELECTION CRITERIA JULY 1, 1998 TO JUNE 30, 1999

	JURISDICTION/AGENCY: CINCINNATI	
	NAME OF PROJECT: WEST FORK RO.	
	PRELIMINARY SCORE FOR THIS PROJECT: 64	
	FINAL SCORE FOR THIS PROJECT:	
	RATING TEAM: 4	
L )	If SCIP/LTIP funds are granted, when would the construction contract be awarded? See Addendum for definition of delinguency	`
	10 Points - Will be under contract by end of 1998 and no delinquent projects in Rounds 9 & 10.	_
	5 Points - Will be under contract by March 30, 1999 and/or jurisdiction has had one delinquent project in Rounds 9 & 10.	
	O Points - Will not be under contract by March 30, 1999 and/or jurisdiction has had more than one delinquent project in Rounds 9 & 10.	
)	What is the physical condition of the existing infrastructure to be replaced or repaired? (See Addendum for definitions)	
	25 Points - Failed 23 Points - Critical 20 Points - Very Poor 17 Points - Poor 15 Points - Moderately Poor 10 Points - Moderately Fair 5 Points - Fair Condition	_
	O Points - Cood or Botton	

NOTE: If the infrastructure is in "good" or better condition, it will  $\underbrace{NOT}$  be considered for SCIP/LTIP funding unless it is an expansion project that will improve serviceability.

3)	If the project is built, what will be its effect on the facility's serviceability? Documentation is required.
	5 Points - Project design is for future demand. 4 Points - Project design is for partial future demand. 5 Points - Project design is for current demand. 6 Points - Project design is for minimal increase in capacity. 7 Point - Project design is for no increase in capacity.
4)	How important is the project to HEALTH, SAFETY, AND WELFARE of the public and the citizens of the District and/or service area? (See Addendum for definitions)
	10 Points - Highly significant importance, with substantial impact on all 3 factors.
	8 Points - Considerably significant importance, with substantial impact on 2 factors, or noticeable impact on all 3 factors
	6 Points - Moderate importance, with substantial impact on 1 factor or noticeable impact on 2 factors.
	4 Points - Minimal importance, with noticeable impact on 1 factor
	2 Points - No measurable impact
5)	What is the overall economic health of the jurisdiction?
	10 Points 8 Points 6 Points 4 Points 2 Points
5)	What matching funds are being committed to the project, expressed as as a percentage of the TOTAL CONSTRUCTION COST? Loan and Credit Enhancement projects automatically receive 5 points, and no match is required. All grant funded projects require a minimum of 10% matching funds.
	5 Points - 50% or more 4 Points - 40% to 49.99% 3 Points - 30% to 39.99% 2 Points - 20% to 29.99% 1 Point - 10% to 19.99%

Has any formal action by a federal, state, or local government agency resulted in a partial or complete ban of the usage or
expansion of the usage for the involved infrastructure? POINTS
MAY ONLY BE AWARDED IF THE END RESULT OF THE PROJECT WILL CAUSE
THE BAN TO BE LIFTED.

5 Points - Complete ban

3 Points - Partial ban

0 Points - No ban of any kind

3

8) What is the total number of existing daily users that will benefit as a result of the proposed project? Appropriate criteria include current traffic counts, households served, when converted to a measurement of persons. Public transit users are permitted to be counted for the roads and bridges, but only when certifiable ridership figures are provided.

5 Points - 16,000 or more

4 Points - 12,000 to 15,999

3 Points - 8,000 to 11,999

2 Points - 4,000 to 7,999

1 Point - 3,999 and under

 $\boldsymbol{Z}$ 

9) Does the infrastructure have regional impact? Consider originations and destinations of traffic, functional classifications, size of service area, number of jurisdictions served, etc. See Addending for definitions.

5 Points - Major impact

1-74 CONNECTION

3 8

4 Points -

3 Points - Moderate impact

2 Points -

1 Point - Minimal or no impact

10) Has the jurisdiction enacted the optional \$5 license plate fee, an infrastructure levy, a user fee, or a dedicated tax for infrastructure and provided certification of which fees have been enacted?

5 Points - Two of the above

3 Points - One of the above

O Points - None of the above

4

# ADDENDUM TO THE RATING SYSTEM DEFINITIONS/CLARIFICATIONS

Criterion 1 - ABILITY TO PROCEED

The Support Staff will assign points based on engineering experience and OPWC defined delinquent projects. A project will be considered delinquent when any of the following occurs: 1) A letter is sent from the OPWC to the affected jurisdiction stating that the project has not moved in accordance with the time frame listed on the application (copies are sent to the District); or 2) no time extension has been granted by the OPWC; or 3) A jurisdiction receiving approval for a project subsequently terminates the same after the bid date on the application. The OPWC sends a letter to a jurisdiction which announces that its' project is going to be terminated when the project is sixty (60) days beyond the bid date shown on the original application and a time extension for the project has not previously been requested or has been denied.

## 2 - CONDITION

Condition is based on the amount of deterioration that is field verified or documented exclusive of capacity, serviceability, or health, safety and welfare issues. Condition is rated only on the existing facility being repaired or abandoned. If the existing facility is not being abandoned or repaired, but a new facility is being built, it shall be considered as an expansion project. (Documentation may include ODOT BR-86 reports, pavement management condition reports, televised underground system reports, age inventory reports, maintenance records, etc., and will only be considered if included with the original application.)

#### Definitions:

FAILED CONDITION - Requires complete reconstruction where no part of the existing facility is salvageable. (e.g. Roads: complete reconstruction of roadway, curbs and base; Bridges: no part of the bridge can be salvaged; Underground: removal and replacement of an underground drainage or water system; Hydrants: completely non-functioning and replacement parts are unavailable.)

<u>CRITICAL CONDITION</u> - Requires moderate or partial reconstruction to maintain integrity. (e.g. Roads: reconstruction of roadway, curbs can be saved; Bridges: only the substructure can be salvaged with modifications; Underground: removal and replacement of part of an underground drainage or water system; Hydrants: some non-functioning, others obsolete and replacement parts are unavailable.)

<u>VERY POOR CONDITION</u> - Requires extensive rehabilitation to maintain integrity. (e.g. Roads: extensive full depth, partial depth and curb repair of a roadway with a structural overlay; Bridges: substructure and superstructure can be salvaged with extensive repairs; Underground: repair of joints and/or minor replacement of pipe sections; Hydrants: non-functioning and replacement parts are available.)

<u>POOR CONDITION</u> - Requires standard rehabilitation to maintain integrity. (e.g. Roads: moderate full depth, partial depth and curb repair to a roadway with no structural overlay needed or structural overlay with minor repairs to a roadway needed; Bridges: deck cannot be salvaged, substructure and superstructure need repair; Underground: insituform or other in ground repairs; Hydrants: functional, but leaking and replacement parts are unavailable.)

MODERATELY POOR CONDITION - Requires minor rehabilitation to maintain integrity. (e.g. Roads: minor full depth, partial depth or curb repairs to a roadway with either a thin overlay or no overlay needed; Bridges: deck can be salvaged with repairs and overlay; Hydrants: functional and replacement parts are available.)

MODERATELY FAIR CONDITION - Requires extensive maintenance to maintain integrity. (e.g. Roads: thin or no overlay with extensive crack sealing, minor partial depth and/or slurry or rejuvenation; Bridges: deck rehabilitation required, overlay not required.)

<u>FAIR CONDITION</u> - Requires routine maintenance to maintain integrity. (e.g. Roads: slurry seal, rejuvenation or routine crack sealing to the roadway; Bridges: minor rehabilitation required.)

GOOD OR BETTER CONDITION - Little or no maintenance required to maintain integrity; Bridges: no work required.

Criterion 4 - HEALTH, SAFETY & WELFARE

#### Definitions:

<u>SAFETY</u> - The design of the project will prevent accidents, promote safer conditions, and eliminate or reduce the danger of risk, liability, or injury.

EXAMPLES: Widening existing roadway lanes to standard lane widths; Adding lanes to a roadway or bridge to increase capacity or alleviate congestion; replacing old or non-functioning hydrants; increasing capacity to a water system, etc.

 ${
m \underline{HEALTH}}$  — The design of the project will improve the overall condition of the facility so as to reduce or eliminate disease; or correct concerns regarding the environmental health of the area.

EXAMPLES: Improving or adding storm drainage or sanitary facilities; replacing lead joints in water lines;

<u>WELFARE</u> - The design of the project will promote economic well-being and prosperity.

EXAMPLES: Project has the potential to improve business expansions or opportunities in the area; project will improve the quality of life in the area;

<u>PLEASE NOTE:</u> The examples listed above are NOT a complete list, but only a small sampling of situations that may be relevant to any given project. Each project is looked at on an individual basis to determine if any aspects of this rating category apply, and if so, to what severity level (minor or significant). The severity and extent of the problem, as it relates to Health, Safety and Welfare, MUST be fully detailed by the applicant and apparent to the rating team. The Support Staff will not attempt to determine these issues on its own. Without such detail the jurisdiction should expect a lower rating than the project may deserve.

Criterion 9 - REGIONAL IMPACT Definitions:

MAJOR IMPACT - Roads: major multi-jurisdictional route, primary feed to an interstate, Federal Aid Primary routes; Underground: primary water or sewer main serving and entire system; Hydrants: multi-jurisdictional.

MODERATE IMPACT - Roads: principal thoroughfares, Federal Aid Urban routes; Underground: primary water or sewer main serving only part of a system; Hydrants: all hydrants in a local system serving only one jurisdiction.

MINIMAL/NO IMPACT - Roads: cul-de-sacs, subdivision streets; Underground: individual water or sewer main not part of a large system; Hydrants: only some hydrants in a local system serving only one jurisdiction.